

5 TIPS: HOW TO KEEP YOUR EQUIPMENT RUNNING

1

Keep your machines **CLEAN** and **FREE** of foreign material.

3

REPLACE parts before they are **WORN** to prevent damage.

5

Conduct **REGULAR INSPECTIONS** to spot potential issues before they arise.

2

Make sure machines are **SETUP** and **ADJUSTED** properly.

4

LUBRICATE regularly as directed by the manufacturer.



401 11th Avenue S., Ste. 100 | Hopkins, MN 55343
952.929.2664 | 1.800.447.5191
info@shippers-supply.com | www.shippers-supply.com

Engineering positive impressions since 1928.